Clear-Com®
AN HME COMPANY

Release Notes

LQ Series v3.0.30

January 25, 2017

I. Introduction

The v3.0.30 is a new software release of the LQ Series software and it supersedes v3.0.27 software.

II. Bug Fixes

A. LQ 4-wire port data pin configuration is not retained on power cycle / LQ not lighting up MVX indicator (#30326)

B. Unable to use LAN/WAN Routed Network linking option (#28777)

C. LQ units stuck in acquiring IP address loop and device unreachable (#27864)