

Release Notes

FreeSpeak Cell Beltpack 2026-01 RELEASE NOTES



Date: May 2026
Release: 2026-01
Doc Part No: PUB-00365 Rev A

FreeSpeak Cell 2026-01 Release Notes

CONTENTS

1	INTRODUCTION	3
1.1	Scope	3
1.2	FreeSpeak Cell Release 2026-01.....	3
1.2.1	Features added in this release.....	3
1.2.2	Enhancements in this release.....	3
1.2.3	Bug Fixes in this release.....	3
1.2.4	Firmware versions of linked or sub-systems – Reference Information only.....	3
1.2.5	Part Number Reference.....	3
1.3	Historical.....	4
2	KNOWN ISSUES	5

REFERENCE LINKS:

Knowledge Center:

<https://www.clearcom.com/Download-Center/Knowledge-Centers>

IMPORANT: COMPATIBILITY NOTE

On Release 2026-01, FreeSpeak Cell Beltpacks are only supported on Eclipse HX System.

On Release 2026-01, eSIM is part of the released Hardware but it is not being supported by Firmware.



LEGAL:

Privacy Statement: <https://www.clearcom.com/Privacy-Statement>

1 Introduction

1.1 Scope

This document describes all releases of FreeSpeak Cell as of 2026.

1.2 FreeSpeak Cell Release 2026-01

Major version including official support for FreeSpeak Cell Beltpack connection to Private Networks (NR5G and LTE 4G).

1.2.1 Features added in this release

-	FreeSpeak Cell Release Support for the FreeSpeak Cell in Eclipse platform. Support for the FreeSpeak Cell connection to NR5G and 4G LTE Private Networks.
---	--

1.2.2 Enhancements in this release

Initial Release

1.2.3 Bug Fixes in this release

N/A

1.2.4 Firmware versions of linked or sub-systems – Reference Information only

While not a part of this release, this FreeSpeak Cell release was tested with devices using the following firmware versions. Please use the below versions, or newer should they be available.

Below firmware versions, or newer, can be found in the Clear-Com’s Download Center

Product	Version
Eclipse HX Matrix Intercom	EHX 15 E-IPA 15.0.0

1.2.5 Part Number Reference

FSC-BP-C-X4
FSC-BP-C-X5

1.2.5.1 Firmware

Part No	Description	File Type	Dev Issue	Production Rev	Last updated in Release
SOF-00325	FW, FSC-BP-C REL APP	ccf	1.0.96.2	C	2026-01
SOF-00326	FW, CELLULAR MODULE REL APP	ccf	1.0.96.1	C	2026-01

FreeSpeak Cell 2026-01 Release Notes

1.2.5.2 Documentation

Part No	Description	Production Rev	Doc Issue	Last updated in Release
PUB-00357	GUIDE, QSG FREESPEAK CELL	A	A	2026-01
PUB-00365	NOTE, FSC RELEASE NOTES	A	A	2026-01

1.3 Historical

No historical references are considered in this Release.

2 Known Issues

This section details those issues that contradict the relevant manuals included in this release. These issues have not been resolved and are listed here to help you use the system more effectively.

ID	Description – Internal Release Notes
222306	Audio routing auto connects to BT headset when it was set to BT Listen In – if the Audio Route “Listen-In” is selected, the route won’t be automatically selected upon a disconnect/re-connect of the Bluetooth headset. Instead, Audio Route will automatically be set to BT headset.
222359	Battery icon indicates “Bad Battery” at Bootup for a second – Not affecting Beltpack’s functionality. A red-outlined-battery Icon is displayed at boot up for a second before first reading.
218800	PIN Request for Menu Access Level not enabled – Beltpack user will be able to navigate between Menu Access Levels without a PIN verification.